



NOTIFICATION TO CUSTOMERS
Please Read this Notice
If you purchased an Eclipse® Receiver from
February 2008 through August 2008, or
If your receiver has a Serial Number ranging
from EDRR 4451 through EDRR 5085

Some Eclipse receivers produced between February and August 2008, consisting of serial numbers EDRR 4451 – EDRR 5085 have a potential issue with two chips on their in-board computers.

A typical symptom is that you cannot put the ball in the box at the locate point. However, this can be an intermittent issue that may resemble interference.

Please contact your local DCI area office or field representative for assistance with resolving this as soon as possible:

DCI Headquarters

19625 62nd Ave. S., Suite B-103
Kent, Washington 98032 USA
Phone 425 251 0559 / 800 288 3610
Fax 253 395 2800
E-mail DCI@digital-control.com

DCI China

No. 41, Lane 500, Xingle Road,
Minhang District, Shanghai 201107
Phone +86(0) 21 6432 5186
Fax +86(0) 21 6432 5187
DCI.China@digital-control.com

DCI Europe

Kurmainzer Strasse 56
D-97836 Bischbrunn, Germany
Phone +49(0) 9394 990 990
Fax +49(0) 9394 990 999
DCI.Europe@digital-control.com

DCI Russia

420059 Pavlyukhina Street
104, Kazan, Russia
Phone +7 843 277 52 22
Fax +7 843 277 52 22
DCI.Russia@digital-control.com

DCI India

SCO # 259, Sector 44-C
Chandigarh (UT) 160 047, Punjab, India
Phone +91(0) 172 464 0444
Fax +91(0) 172 464 0999
DCI.India@digital-control.com

DCI Australia

2/9 Frinton Street, Southport
Queensland 4215, Australia
Phone +61(0) 7 5531 4283
Fax +61(0) 7 5531 2617
DCI.Australia@digital-control.com

www.digitrak.com